



Birchwood 400 Crusader

£114,950.00

**LYING NYA BRUNDALL - NYB62347 -
P/EX POSSIBLE**

BIRCHWOOD 400 CRUSADER - 2000 - Powered by twin Mercruiser D-Tronic 250 diesels. 6 berth accommodation with 2 toilets and 2 showers. Specification to include; Holding tank, Warm air heating, electric windlass, Tracvision, a range of navigation equipment and shore power supply with charger. Folding radar arch and teak laid cockpit, steps and bathing platform. Fully prepared by NYA to include, recent full machine polish, engine service and antifoul. A lightly used Birchwood 400 with very low engine hours.

Manufacturer:	Birchwood	LOA:	41' 2" (12.56m)
Model:	400	Beam:	12' 2" (03.73m)
Year:	2000	Draft:	3' 4" (01.04m)
Construction:	GRP	Type:	Motor Cruiser
Hull/Kell Type:	Planing	Berths/Cabins:	0 Berths in 0 Cabins
Engines:	2 x 250HP, Mercruiser	Showers/Toilets:	0 Showers, 0 Toilets
		Fuel Type:	Diesel
		Drive Type:	Shafts



Interior overview



Island double aft cabin

ACCOMMODATION

GALLEY

- Galley to starboard to include;
- Smev oven and grill
- 4 burner hob

- Large refrigerator
 - Twin sink unit
 - Ample stowage
-

OTHER EQUIPMENT

- Ropes and fenders
- Sony CD/Radio player

MECHANICAL ELECTRICAL

- Holding tank
- Battery charger
- Electric windlass
- Trim tabs
- Tracvision
- Eberspacher warm air heating
- 240v sockets
- 12v sockets
- Glomex TV booster
- Wipers
- Engine instruments

NAVIGATION

- Raytheon RL70
- Raytheon autopilot
- VHF
- Compass
- Spotlight
- Navigation lights

SAFETY EQUIPMENT

- Fire blanket
 - Fire extinguisher
-

DECK EQUIPMENT

- Boarding ladder
- Cleats
- Transom shower
- Guard rails
- Grab rails
- Fender baskets
- Cockpit canopy
- Flybridge cruiser

SERVICE HISTORY

- Engine service 2018
- Full machine polish 2018
- Antifoul 2018

COMMENTS

Part exchange possible

DISCLAIMER

The company normally acts as broker for the vendor who unless otherwise stated is not selling in the course of a business. Whilst every care has been taken in the preparation of these particulars the correctness is not guaranteed and they are intended as a guide only and do not constitute a part of any contract. A prospective buyer is strongly advised to check these particulars and where appropriate and at his own expense to employ a qualified marine surveyor to carry out a survey and/or to have an engine trial conducted which if conducted by us shall not imply any liability on our part.



Interior overview



Saloon seating and helm to starboard



Well equipped galley to port



Island double aft cabin



Forward twin bunks



Dining area and galley



Forward heads



Aft cockpit