



Sealine F43

£144,950.00

LYING NYA BRUNDALL - NYB69207 - P/EX POSSIBLE

SEALINE F43 - 2003 - Powered by twin Volvo TAMD75p 480hp diesels. 6 berth accommodation with two toilets and two showers. Specification to include; Generator, bowthruster, warm air heating, electric windlass and a full range of Raymarine navigation equipment. Teak laid cockpit and bathing platform. A very well-kept example benefiting from investment by her current owner including new battery charger and inverter plus engine service, antifoul and generator service in 2018!

Manufacturer:	498, Sealine	LOA:	43' 5" (13.24m)
Model:	F43	Beam:	13' 5" (04.11m)
Year:	2003	Draft:	4' 1" (01.25m)
Construction:	GRP	Type:	Motor Cruiser
Hull/Kell Type:	Planing	Berths/Cabins:	6 Berths in 2 Cabins
Engines:	2 x 480HP, Volvo	Showers/Toilets:	2 Showers, 2 Toilets
		Fuel Type:	Diesel
		Drive Type:	Shafts



ACCOMMODATION

- SEALINE F43

GALLEY

- Galley to port to include;
- Smev oven and grill
- Waeco refrigerator (New 2018)
- Stainless steel sink and mixer tap
- Eno 3 burner hob
- Ample stowage

OTHER EQUIPMENT

- Lifting TV in saloon
- Pioneer CD/Radio player
- Ropes and fenders

MECHANICAL ELECTRICAL

- Generator
- Bowthruster
- Warm air heating
- Electric windlass
- Trim tabs
- Shore power
- 240v sockets
- Battery charger
- Calorifier
- 12v sockets
- Bilge pumps

NAVIGATION

- Raymarine RL70C
- Raymarine RC530
- Raymarine ST6001+ Autopilot
- Raymarine speed and depth logs
- Raymarine VHF
- Compass
- Rudder indicator
- Horn

SAFETY EQUIPMENT

- Fire extinguishers
- Fire blanket

DECK EQUIPMENT

- Teak laid bathing platform and cockpit
- Anchor
- Guard rails
- Grab rails
- Deck cleats
- Cockpit canopy
- Bimini cover
- Davits
- Boarding ladder

SERVICE HISTORY

- Engine service 2018
- Recent antifoul
- Generator service 2018
- New stern glands
- New smart TV
- Sterling battery charger
- New domestic water pump

COMMENTS

Part exchange possible

DISCLAIMER

The company normally acts as broker for the vendor who unless otherwise stated is not selling in the course of a business. Whilst every care has been taken in the preparation of these particulars the correctness is not guaranteed and they are intended as a guide only and do not constitute a part of any contract. A prospective buyer is strongly advised to check these particulars and where appropriate and at his own expense to employ a qualified marine surveyor to carry out a survey and/or to have an engine trial conducted which if conducted by us shall not imply any liability on our part.



