



## Broom 9/70

**£54,950.00**

**LYING CONTACT NYA BRUNDALL - NYH62229 - P/EX  
POSSIBLE**

Broom [9/70 - 1987](#) - Powered by twin 130hp Volvo diesels. 6 berth accommodation with 2 toilets and 2 showers. BSC 07/20. Specification to include; holding tank, warm air heating and shore power supply with battery charger. Folding screens for good inland access. In current ownership for 17 years cruising various waterways. A nice original 9/70, presented in good order for her age.

Manufacturer:	Broom	LOA:	32' 0" (09.76m)
Model:	9/70	Beam:	12' 0" (03.66m)
Year:	1987	Draft:	2' 11" (00.90m)
Construction:	GRP	Type:	Motor Cruiser
Hull/Kell Type:	Semi-Displacement	Berths/Cabins:	6 Berths in 2 Cabins
Fuel Capacity:	545.53	Showers/Toilets:	2 Showers, 2 Toilets
Engines:	2 x 130HP, Volvo	Fuel Type:	Diesel
		Drive Type:	Shafts



Interior overview



Forward V-berth

## GALLEY

- Galley to starboard to include;
- 2 burner hob, oven and grill
- Refrigerator
- Microwave
- Ample stowage

## OTHER EQUIPMENT

- Radio

## MECHANICAL ELECTRICAL

- Holding tank
- Warm air heating
- Shore power
- Battery charger
- Calorifier
- 240v sockets
- 12v socket
- bilge pump
- Wipers
- Engine instruments

## NAVIGATION

- Echosounder
- Magellan Nav6500
- VHF
- Horn
- Navigation lights
- Compass

## SAFETY EQUIPMENT

- Fire extinguishers
- Fire blanket
- Life buoy

## DECK EQUIPMENT

- Fender baskets
- Screen cover
- Extended canopy
- Cleats
- Boarding ladder
- Bathing platform
- Windlass
- Anchor
- Full guard rails
- Grab rails
- Davit
- Light mast

## SERVICE HISTORY

- Maintained by owner

## COMMENTS

Part exchange possible

## DISCLAIMER

The company normally acts as broker for the vendor who unless otherwise stated is not selling in the course of a business. Whilst every care has been taken in the preparation of these particulars the correctness is not guaranteed and they are intended as a guide only and do not constitute a part of any contract. A prospective buyer is strongly advised to check these particulars and where appropriate and at his own expense to employ a qualified marine surveyor to carry out a survey and/or to have an engine trial conducted which if conducted by us shall not imply any liability on our part.





Interior overview



Cockpit seating



Upper helm to port



Galley to starboard



Forward V-berth



Forward heads

